

## Transmitter Firmware – Change Notes

21.01.2025

The changes applied to transmitter firmware and corresponding versioning are as followed. please be noted that these updates, enhancement or fixes have no impact on the measurement result.

### M200 (52121554, 52121556, 52121555, 52121557)

FW Version	Release Date	Description
V 2.2.01	2021/Jan/6	▪ Bug fixed: Measurement is wrong at high concentrations for Pure O <sub>3</sub> sensor
V 2.2.00	2016/Oct/18	▪ Added: new Pure O <sub>3</sub> sensor
V 2.1.01	2016/Jun/1	▪ Added: USB commands for Transmitter Configuration Tool
V 2.0.00	2015/Dec/30	▪ Added: M200 to ISM sensors